DISTRICT RADON REPORT

IN ACCORDANCE TO ORS 332.166-167

PREPARED FOR: THE BANDON SCHOOL DISTRICT 455 9th St SW Bandon, OR 97411

> Ocean Crest ELEMENTARY 1040 Allegheny Ave SW Bandon, OR 97411

Harbor Lights Middle School 390 9th St SW Bandon, OR 97411

ADMINISTRATIVE OFFICES 455 9th St SW Bandon, OR 97411



April 23rd 2018

Hiemer Kiefer- Director of Operations Bandon School District 455 9th St SW Bandon, OR 97411

Via email: hiemerk@bandon.k12.or.us

Regarding: District-Wide Radon Testing

Bandon School District

455 9th St SW Bandon, OR 97411 EIS Project 201819

Dear Mr. Kiefer:

From March 28th to March 30th, 2018, Environmental Inspection Services (EIS) performed short-term radon testing at the Bandon School District buildings located at:

- OCEAN CREST ELEMENTARY 1040 ALLEGHENY AVE SW, BANDON, OR 97411
- HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW, BANDON, OR 97411
- ADMINISTRATIVE OFFICES & MAIN GYM 455 9TH ST SW, BANDON, OR 97411

The Environmental Protection Agency (EPA) and Oregon Health Authority (OHA) recommend that buildings be tested for radon and that any radon concentrations be maintained below 4.0 picocuries per liter (pCi/L) of air. EIS used Pro-Lab brand single-use, short-term radon test kits to measure radon levels in frequently-occupied rooms that are in contact with the ground or above unoccupied basements or crawlspaces.

Laboratory results indicate that all short-term radon tests at the following locations were below 4.0 pCi/L.

- OCEAN CREST ELEMENTARY 1040 ALLEGHENY AVE SW, BANDON, OR 97411
- HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW, BANDON, OR 97411
- ADMINISTRATIVE OFFICES & MAIN GYM 455 9TH ST SW, BANDON, OR 97411

*See the attached laboratory analysis report for more details.



In addition to the EPA recommendation that radon concentrations not exceed 4.0 pCi/L, OHA recommends that the following steps be conducted based on the results of a room's initial short-term test:

If the result is less than 2.0 pCi/L, school districts are required to test again every 10 years, per Oregon Revised Statute 332.166-167.

If the result is between 2.0 pCi/L and 4.0 pCi/L, consider fixing (i.e., lowering) the radon in that room.

The following locations were between 2.0 pCi/L and 4.0 pCi/L.

Laboratory results indicate that there were NO tests exceeding 4.0 pCi/L.

*See the attached laboratory analysis report for more details.

If the result is from 4.0 pCi/L to 8.0 pCi/L, perform a follow-up measurement of that room using a long-term test. This test should be conducted over as much of a nine-month school year as possible, when the room is likely to be occupied. If that result is equal to or greater than 4.0 pCi/L, the radon in the room should be fixed (i.e., lowered).

Laboratory results indicate that there were NO tests exceeding 4.0 pCi/L.

*See the attached laboratory analysis report for more details.

If the initial short-term test result is equal to or greater than 8.0 pCi/L, conduct a second short-term test and average its result with the initial short-term test result. If the average of the two is equal to or greater than 4.0 pCi/L, radon in the room should be fixed (i.e., lowered).

Laboratory results indicate that there were NO tests exceeding 8.0 pCi/L.

*See the attached laboratory analysis report for more details.



LAB ANALYSIS FOR:

OCEAN CREST ELEMENTARY 1040 ALLEGHENY AVE SW BANDON, OR 97411





1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163376 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 OCEAN CREST ELEMENTARY 1040 ALLEGANY COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4525685

2ND FLOOR OFFICE Mar 28, 2018 12:52 PM Mar 30, 2018 1:19 PM Apr 08, 2018 4:38 AM 0.3 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163378 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 OCEAN CREST ELEMENTARY 1040 ALLEGANY COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL # ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED RA

RADON LEVEL

4525667

BASEMENT OFFICE Mar 28, 2018 12:57 PM Mar 30, 2018 1:19 PM Apr 08, 2018 4:28 AM 0.3 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV

James & M. Darel



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163381 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 OCEAN CREST ELEMENTARY 1040 ALLEGANY COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL # ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4525888

BASEMENT OFFICE Mar 28, 2018 12:57 PM Mar 30, 2018 1:19 PM Apr 08, 2018 6:15 AM 0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163384 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 OCEAN CREST ELEMENTARY 1040 ALLEGANY COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4525671

BASEMENT OFFICE Mar 28, 2018 12:58 PM Mar 30, 2018 1:20 PM Apr 08, 2018 4:55 AM 0.3 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV

James & M. Darel



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163386 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 OCEAN CREST ELEMENTARY 1040 ALLEGANY COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4607938

2ND FLOOR GYM Mar 28, 2018 12:44 PM Mar 30, 2018 1:15 PM Apr 08, 2018 6:25 AM 0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV

James & M. Darel



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163388 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 OCEAN CREST ELEMENTARY 1040 ALLEGANY COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4525794

2ND FLOOR GYM Mar 28, 2018 12:45 PM Mar 30, 2018 1:16 PM Apr 08, 2018 1:51 AM 0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163392 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 OCEAN CREST ELEMENTARY 1040 ALLEGANY COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4525976

2ND FLOOR GYM Mar 28, 2018 12:47 PM Mar 30, 2018 1:16 PM Apr 08, 2018 1:41 AM 0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV

James & M. Darel



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163394 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 OCEAN CREST ELEMENTARY 1040 ALLEGANY COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4568722

2ND FLOOR GYM Mar 28, 2018 12:50 PM Mar 30, 2018 1:18 PM Apr 08, 2018 6:39 AM 0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163403 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/11/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 OCEAN CREST ELEMENTARY 1040 ALLEGANY COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4337179

2ND FLOOR STAFF Mar 28, 2018 12:36 PM Mar 30, 2018 1:18 PM Apr 08, 2018 5:05 AM 0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163405 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/11/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 OCEAN CREST ELEMENTARY 1040 ALLEGANY COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4525989

2ND FLOOR COUNSELOR

Mar 28, 2018 12:38 PM Mar 30, 2018 1:13 PM Apr 08, 2018 5:55 AM 0.3 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163409 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/11/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 OCEAN CREST ELEMENTARY 1040 ALLEGANY COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4453274

BASEMENT

Mar 28, 2018 12:42 PM Mar 30, 2018 1:15 PM Apr 08, 2018 6:05 AM 0.4 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV

James & M. Darel



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163398 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/11/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICES - AURO 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 OCEAN CREST ELEMENTARY 1040 ALLEGANY COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4525730

2ND FLOOR OFFICE FRONT Mar 28, 2018 12:33 PM Mar 30, 2018 1:14 PM Apr 08, 2018 6:49 AM 0.4 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV

LAB ANALYSIS FOR:

HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW BANDON, OR 97411





1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163170 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL # ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4533383

2ND FLOOR LIBRARY-7 Mar 28, 2018 11:40 AM Mar 30, 2018 12:42 PM Apr 07, 2018 4:18 AM 1.5 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163177 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4607968

2ND FLOOR LIBRARY-8TH Mar 28, 2018 11:43 AM Mar 30, 2018 12:40 PM Apr 07, 2018 4:08 AM 1.5 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV

James & M. Darel



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163181 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL # ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4533382

2ND FLOOR OFFICE Mar 28, 2018 11:58 AM Mar 30, 2018 12:50 PM Apr 07, 2018 1:06 PM 0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV

James & M. Darel



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163189 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4525830

2ND FLOOR OFFICE Mar 28, 2018 11:58 AM Mar 30, 2018 12:52 PM Apr 07, 2018 3:58 AM 0.5 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV

James & M. Darel



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

> **TEST ID NUMBER:** 1163195 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST. AURORA, OR 97002

HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED RADON LEVEL

4525935

2ND FLOOR GYM-CLASS 8 Mar 28 2018 11:42 AM

Mar 30, 2018 12:39 PM

Apr 07, 2018 10:11 PM

0.7 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035

PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

> **TEST ID NUMBER:** 1163199 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST. AURORA, OR 97002

HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED RADON LEVEL

4525691

2ND FLOOR **BOYS LOCKER** Mar 28 2018 11:55 AM

Mar 30, 2018 12:50 PM

Apr 07, 2018 10:21 PM

0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035

PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

> **TEST ID NUMBER:** 1163204 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST. AURORA, OR 97002

HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL# **ROOM TESTED** DATE OPENED

DATE CAPPED

DATE ANALYZED RADON LEVEL

4525998

BASEMENT OFFICE

Mar 28 2018 11:58 AM

Mar 30, 2018 12:53 PM

Apr 07, 2018 10:32 PM

0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035

PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

> **TEST ID NUMBER:** 1163206 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST. AURORA, OR 97002

HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED RADON LEVEL

4525665

BASEMENT OFFICE

Mar 28 2018 11:58 AM

Mar 30, 2018 12:50 PM

Apr 07, 2018 10:43 PM

0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035

PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV

James & M. Darel



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

> **TEST ID NUMBER:** 1163210 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST. AURORA, OR 97002

HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED RADON LEVEL

4607995

2ND FLOOR GYM-13

Mar 28 2018 11:31 AM

Mar 30, 2018 12:40 PM

Apr 07, 2018 10:54 PM

0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035

PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV

James & M. Darel



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

> **TEST ID NUMBER:** 1163223 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST. AURORA, OR 97002

HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED RADON LEVEL

4525728

2ND FLOOR OFFICE

Mar 28 2018 11:34 AM

Mar 30, 2018 12:43 PM

Apr 07, 2018 11:15 PM

1.5 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035

PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV

James & M. Darel



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

> **TEST ID NUMBER:** 1163226 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST. AURORA, OR 97002

HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED RADON LEVEL

4607929

2ND FLOOR LIBRARY

Mar 28 2018 11:35 AM

Mar 30, 2018 12:42 PM

Apr 07, 2018 11:26 PM

1.3 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035

PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV

James & M. Darel



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

> **TEST ID NUMBER:** 1163230 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST. AURORA, OR 97002

HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED RADON LEVEL

4607990

2ND FLOOR OFFICE

Mar 28 2018 12:00 PM

Mar 30, 2018 12:53 PM

Apr 08, 2018 12:20 AM

0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035

PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

> **TEST ID NUMBER:** 1163240 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST. AURORA, OR 97002

HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED RADON LEVEL

4525929

2ND FLOOR OFFICE

Mar 28 2018 12:01 PM

Mar 30, 2018 12:40 PM

Apr 08, 2018 12:41 AM

0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035

PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV

James & M. Darel



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163244 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4453115

2ND FLOOR GYM Mar 28, 2018 11:30 AM

Mar 30, 2018 12:36 PM Apr 08, 2018 12:52 AM 0.7 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163249 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4525778

2ND FLOOR GYM Mar 28, 2018 11:36 AM Mar 30, 2018 12:36 PM Apr 08, 2018 12:57 AM 0.7 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV

James & M. Smell



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163250 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4453073

2ND FLOOR GYM Mar 28, 2018 11:37 AM Mar 30, 2018 12:36 PM Apr 08, 2018 1:07 AM 0.3 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163255 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4525952

2ND FLOOR GYM Mar 28, 2018 11:40 AM

Mar 30, 2018 12:39 PM Apr 08, 2018 1:17 AM 1.0 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163262 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4453247

2ND FLOOR GYM Mar 28, 2018 11:50 AM Mar 30, 2018 12:46 PM Apr 08, 2018 1:27 AM 0.4 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163268 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002

HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4453324

2ND FLOOR GYM Mar 28, 2018 11:58 AM Mar 30, 2018 12:46 PM Apr 08, 2018 1:37 AM 0.4 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163272 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002

HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4453240

2ND FLOOR GYM Mar 28, 2018 11:55 AM Mar 30, 2018 12:40 PM Apr 08, 2018 1:47 AM 0.6 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163278 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4525891

2ND FLOOR GYM Mar 28, 2018 11:57 AM Mar 30, 2018 12:47 PM Apr 08, 2018 1:57 AM 0.4 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV

James & M. Darel



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163285 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4533396

2ND FLOOR GYM Mar 28, 2018 12:40 PM Mar 30, 2018 12:48 PM Apr 08, 2018 2:07 AM 0.4 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163289 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4525682

2ND FLOOR GYM Mar 28, 2018 12:01 PM Mar 30, 2018 12:48 PM Apr 08, 2018 2:27 AM 0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163305 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4525737

2ND FLOOR GYM Mar 28, 2018 12:03 PM Mar 30, 2018 12:48 PM Apr 08, 2018 2:48 AM 0.3 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV

James & M. Darel



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163214 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICES - AURO 11981 FARGO RD AURORA, OR 97002 HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4337176

2ND FLOOR GYM-14 Mar 28, 2018 11:33 AM Mar 30, 2018 12:36 PM Apr 07, 2018 11:04 PM 1.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163235 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICES - AURO 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 HARBOR LIGHTS MIDDLE SCHOOL 390 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4607940

2ND FLOOR OFFICE

Mar 28, 2018 12:00 PM Mar 30, 2018 12:52 PM Apr 08, 2018 12:30 AM 0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV

LAB ANALYSIS FOR:

ADMINISTRATIVE OFFICES 455 9TH ST SW BANDON, OR 97411





1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163154 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 BANDON SD 54 ADMINISTRATION 455 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4525898

2ND FLOOR OFFICE-MAIN Mar 28, 2018 10:35 AM Mar 30, 2018 11:58 AM Apr 07, 2018 4:48 AM 0.4 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163160 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 BANDON SD54 ADMINISTRATION 455 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4525780

2ND FLOOR OFFICE-GED

Mar 28, 2018 10:36 AM Mar 30, 2018 11:58 AM Apr 07, 2018 4:38 AM 0.4 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV

James & M. Darel



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

TEST ID NUMBER: 1163164 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/10/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST, AURORA, OR 97002 BANDON SD54 ADMINISTRATION 455 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED

RADON LEVEL

4607941

2ND FLOOR GYM-DOUG ARDIANT Mar 28, 2018 10:30 AM Mar 30, 2018 11:58 AM Apr 07, 2018 4:28 AM 0.4 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035 PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV

James & M. Darel



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

> **TEST ID NUMBER:** 1163427 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/11/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST. AURORA, OR 97002

BANDON MAIN GYM 455 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED RADON LEVEL

4453260

2ND FLOOR MAIN OFFICE Mar 28 2018 12:13 PM

Mar 30, 2018 1:01 PM

Apr 07, 2018 10:44 PM

0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035

PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

> **TEST ID NUMBER:** 1163431 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/11/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST. AURORA, OR 97002

BANDON MAIN GYM 455 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL# **ROOM TESTED** DATE OPENED

DATE CAPPED

DATE ANALYZED RADON LEVEL

4337194

BASEMENT OFFICE

Mar 28 2018 12:15 PM

Mar 30, 2018 1:01 PM

Apr 07, 2018 10:54 PM

0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035

PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

> **TEST ID NUMBER:** 1163437 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/11/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST. AURORA, OR 97002

BANDON MAIN GYM 455 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL# **ROOM TESTED** DATE OPENED

DATE CAPPED

DATE ANALYZED RADON LEVEL

4525821

BASEMENT OFFICE

Mar 28 2018 12:16 PM

Mar 30, 2018 1:02 PM

Apr 07, 2018 11:16 PM

0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035

PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

> **TEST ID NUMBER:** 1163442 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/11/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST. AURORA, OR 97002

BANDON MAIN GYM 455 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED RADON LEVEL

4525874

2ND FLOOR OTHER

Mar 28 2018 12:15 PM

Mar 30, 2018 1:00 PM

Apr 09, 2018 11:37 AM

0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035

PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

> **TEST ID NUMBER:** 1163447 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/11/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST. AURORA, OR 97002

BANDON MAIN GYM 455 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED RADON LEVEL

4607947

BASEMENT OFFICE

Mar 28 2018 12:10 PM

Mar 30, 2018 1:03 PM

Apr 09, 2018 11:27 AM

0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035

PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

> **TEST ID NUMBER:** 1163450 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/11/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST. AURORA, OR 97002

BANDON MAIN GYM 455 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL# **ROOM TESTED** DATE OPENED

DATE CAPPED

DATE ANALYZED RADON LEVEL

4525669

BASEMENT OFFICE

Mar 28 2018 12:11 PM

Mar 30, 2018 1:03 PM

Apr 09, 2018 11:17 AM

0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035

PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

> **TEST ID NUMBER:** 1163453 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/11/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST. AURORA, OR 97002

BANDON MAIN GYM 455 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL#

ROOM TESTED

DATE OPENED

DATE CAPPED

DATE ANALYZED RADON LEVEL

4525766

BASEMENT OFFICE

Mar 28 2018 12:12 PM

Mar 30, 2018 1:04 PM

Apr 09, 2018 10:49 AM

0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035

PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV



1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

> **TEST ID NUMBER:** 1163457 **DATE RECEIVED:** 04/06/2018 **REPORT DATE:** 04/11/2018

TEST LOCATION

ENVIRONMENTAL INSPECTION SERVICE, INC. 11981 FARGO ROAD NORTHEAST. AURORA, OR 97002

BANDON MAIN GYM 455 9TH ST SW COOS COUNTY BANDON, OR 97411

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

VIAL# **ROOM TESTED** DATE OPENED

DATE CAPPED

DATE ANALYZED RADON LEVEL

4525939

BASEMENT OTHER

Mar 28 2018 12:13 PM

Mar 30, 2018 1:00 PM

Apr 09, 2018 10:38 AM

0.2 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCI/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at http://njradon.org/download/mitbas.pdf. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (971) 673-0490.

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Malissa Sears, RMS

Malissa Sears

NRPP CERT# 104126RT NRSB CERT # 6SS0035

PRO-LAB NRSB # ARL0028 PRO-LAB NEHA ID # 101461AL James E. McDonnell IV