

# Radon Testing Results - Administrative Offices

## Action Level is 4.0 pCi/L

| Site Name              | Building Name | Room Description<br>(per floor plan) | Kit serial # | Date sampled | Type of test | Results<br>(pCi/L) |
|------------------------|---------------|--------------------------------------|--------------|--------------|--------------|--------------------|
| Administrative Offices | Main Building | 2nd Floor Office Main                | 4525898      | 3/28/2018    | Detector Kit | 0.4                |
| Administrative Offices | Main Building | 2nd Floor Office GED                 | 4525780      | 3/28/2018    | Detector Kit | 0.4                |
| Administrative Offices | Main Building | 2nd Floor Supt Office                | 4607941      | 3/28/2018    | Detector Kit | 0.4                |
| Administrative Offices | Main Building | 2nd Floor Main Office                | 4453260      | 3/28/2018    | Detector Kit | 0.2                |